

Appendix C

Errata from 2001 Report

The following information was reported incorrectly in the *Savannah River Site Environmental Report for 2001* (WSRC-TR-2001-00474):

Chapter 3 (“Radiological Effluent Monitoring”), Airborne Emissions section; chapter 5 (“Potential Radiation Doses”), Air Pathway section; and supporting tables: Because of an analytical error, the amount of iodine-129 in site releases during 2001

was reported inaccurately. The actual 2001 iodine-129 release total from the separations areas was 2.78E-02 curies (compared with the 1.29E-02 curies reported). For complete revised results, refer to the “Errata” folder on the CD accompanying this report.

Errata from 2000 Report

The following information was reported incorrectly in the *Savannah River Site Environmental Report for 2000* (WSRC-TR-2000-00328):

Chapter 5 (“Radiological Effluent Monitoring”), Airborne Emissions section; chapter 7 (“Potential Radiation Doses”), Air Pathway section; and supporting tables: Because of an analytical error, the amount of iodine-129 in site releases during 2000

was reported inaccurately. The actual 2000 iodine-129 release total from the separations areas was 2.05E-02 curies (compared with the zero curies reported). For complete revised results, refer to the “Errata” folder on the CD accompanying this report.